

REGULATORY ACTIVITY SUMMARY

NAME Paul Mullen and 1911821 Ontario Inc. LICENSURE STATUS AT THE TIME OF INCIDENT ADMINISTRATIVE ACTION Conviction after Trial LOCATION Barrie Provincial Offences Court REGULATION DESCRIPTION 1. Did operate an electrical contracting business without being the holder of an Electrical Contractor Licence contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000. 1911821 Ontario Inc, was convicted and fined \$2,500.		
LICENSURE STATUS AT THE TIME OF INCIDENT ADMINISTRATIVE ACTION Conviction after Trial LOCATION Barrie Provincial Offences Court REGULATION DESCRIPTION OF The Contractor Licence Contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000.	DATE	March 8, 2023
LICENSURE STATUS AT THE TIME OF INCIDENT ADMINISTRATIVE ACTION Conviction after Trial LOCATION Barrie Provincial Offences Court REGULATION DESCRIPTION OF The Contractor Licence Contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000.		
THE TIME OF INCIDENT ADMINISTRATIVE ACTION Conviction after Trial LOCATION Barrie Provincial Offences Court 1. Did operate an electrical contracting business without being the holder of an Electrical Contractor Licence contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000.	NAME	Paul Mullen and 1911821 Ontario Inc.
LOCATION Barrie Provincial Offences Court 1. Did operate an electrical contracting business without being the holder of an Electrical Contractor Licence contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000.		Unlicensed
REGULATION DESCRIPTION 1. Did operate an electrical contracting business without being the holder of an Electrical Contractor Licence contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000.	ADMINISTRATIVE ACTION	Conviction after Trial
an Electrical Contractor Licence contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the Electricity Act. Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months. 1911821 Ontario Inc. was convicted and fined \$6,000. 2. Did fail to file with the Inspection Department, application for inspection of work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the Electricity Act. Paul Mullen was convicted and fined \$3,000.	LOCATION	Barrie Provincial Offences Court
work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the <i>Electricity Act</i> . Paul Mullen was convicted and fined \$3,000.	_	an Electrical Contractor Licence contrary to s. 3 of Ontario Regulation 570/05 and did thereby commit an offence contrary to s. 113.20(1)(d) of the <i>Electricity Act</i> . Paul Mullen was convicted and fined \$7,000 and placed on probation for 24 months.
l		work on an electrical installation located at 5546 Concession Road #2, Sunnidale, New Lowell, Ontario, as required by the provisions of Rule 2-004(1) of the Ontario Electrical Safety Code, adopted by reference in Ontario Regulation 164/99, as amended, and did thereby commit an offence contrary to s.113.20(1)(a) of the <i>Electricity Act</i> . Paul Mullen was convicted and fined \$3,000.

DESCRIPTION OF CONTRAVENTION

1. No Electrical Contractor's Licence.

In the spring of 2019, the homeowner of 5546 Concession Road 2, Sunnidale, Clearview, contracted with Paul Mullen and 1911821 Ontario Inc. to replace a generator. Paul Mullen and 1911821 Ontario Inc. provided and installed the new generator. The installation included the replacement of existing electrical wiring that ran from the generator into the basement and into the transfer



REGULATORY ACTIVITY SUMMARY

switch. The homeowner observed the electrical work, specifically, the homeowner observed the workers pulling the electrical wiring into the basement and into the transfer switch.

Neither Paul Mullen nor 1911821 Ontario Inc. held an electrical contractor's licence which is required to operate a business which does electrical work.

2. Fail to Notify Work Requiring an Inspection.

In the Spring of 2019, Paul Mullen and 1911821 Ontario Inc., contracted with the homeowner of 5546 Concession Road 2, Sunnidale, Clearview for the installation of a replacement generator. The installation of the replacement generator and the associated electrical work required an inspection by the Electrical Safety Authority. Paul Mullen and 1911821 Ontario Inc. failed to notify the Electrical Safety Authority within 24 hours of commencing the work to replace the generator. It was only when the homeowner made inquiries after the installation of the generator about the inspection permit, did the Electrical Safety Authority attend the residence and detect the offences.

ADDITIONAL INFORMATION