

Misrepresentation of Intertek Certified Product / Représentation erronée du produit certifié Intertek

Grid Support Hybrid inverter, model SPF 12000T DVM-US MPV

Notification Type:	Misuse of Certification Mark / Mauvaise utilisation des marques de certification
Certification Type:	ETL Listed - US and Canada

Notification

Intertek notifies consumers, retailers and distributors of products in the marketplace that are bearing counterfeit Intertek Certification Marks as identified below. / Intertek informe les consommateurs, les détaillants et les distributeurs de produits sur le marché qui portent des marques de certification Intertek contrefaites comme indiqué ci-dessous.

Company Identification

Shenzhen Growatt New Energy Co

Product Identification

A safety concern of certified product of Shenzhen Growatt New Energy, model SPF 12000T DVM-US MPV, and product is labeled and using a cETLus Certification Mark control number 4003184. Specifically, a lot of 300 units were produced using a junction box that is not identified in Intertek documentation. Label photo on Page 2.

Un problème de sécurité concerne un produit certifié de Shenzhen Growatt New Energy (modèle SPF 12000T DVM-US MPV). Ce produit est étiqueté et porte la marque de certification cETLus numéro 4003184. Plus précisément, un lot de 300 unités a été produit à l'aide d'une boîte de jonction non identifiée dans la documentation Intertek. Photo de l'étiquette en page 2.

Hazard Involved

Not certified by Intertek. / Non certifié par Intertek.

What To Do

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.

Published: May 14, 2025
Revised:

Public Notice ID: 2025-46
Page 2 of 2

Photos and Images / Photos et images

