

## **Administrative Action Summary**

Date	November 25, 2024
Name	Alp Selcuk
Licensure Status at Time of Incident	Unlicensed
Administrative Action	Administrative Penalty
Location	Etobicoke
Regulation Description	<ol> <li>Carried out, or in the alternative permitted or employed the carrying out of, of an activity referred to in the regulations under the <i>Electricity Act, 1998</i> as requiring an authorization, by carrying out electrical work at a residential property located in Toronto, without being authorized, contrary to ss.113.2(1) of the <i>Electricity Act, 1998</i>.</li> </ol>
	Alp Selcuk was ordered to pay an administrative penalty of \$3,000.
	<ol> <li>Prior to the commencement of work to be done on an electrical installation at a residential property in Toronto, failed to file with Electrical Safety Authority a notification of the work, contrary to rule 2-004(1)(a) of the Ontario Electrical Safety Code.</li> </ol>
	Alp Selcuk was ordered to pay an administrative penalty of \$2,500.



Description of Contravention	Alp Selcuk (" <b>Selcuk</b> ") was not authorized to carry out electrical work.
	Between October 1 <sup>st</sup> and December 31 <sup>st</sup> , 2023, Selcuk carried out, or in the alternative permitted or employed someone to carry out, electrical work at a residential property located in Toronto. In doing so Selcuk failed to file with Electrical Safety Authority a notification of the work, colloquially known as a permit.
Additional Information	