

Administrative Action Summary

Date	July 21, 2025
Name	Campoli Electric Ltd.
Licensure Status at Time of Incident	Licensed
Administrative Action	Administrative Penalty
Location	Mississauga
Regulation Description	Connected or reconnected an electrical installation or part thereof to a service or other source of supply without a connection authorization having been issued by the Electrical Safety Authority, ("ESA"), contrary to Rule 2-012 of the Ontario Electrical Safety Code.
	Campoli Electric Ltd., was ordered to pay an administrative penalty of \$2,500.
	2. Removed a tag, seal or warning applied to an electrical installation or applied to electrical equipment from the electrical installation or equipment without permission from the ESA, contrary to Rule 2-032(4) of the Ontario Electrical Safety Code.
	Campoli Electric Ltd., was ordered to pay an administrative penalty of \$1,000.
	3. Connected or reconnected an electrical installation or part thereof to a service or other source of supply without a connection authorization having been issued by the ESA, contrary to Rule 2-012 of the Ontario Electrical Safety Code.
	Campoli Electric Ltd., was ordered to pay an administrative penalty of \$2,500.
	4. Removed a tag, seal or warning applied to an electrical installation or applied to electrical equipment from the electrical installation or equipment without permission from the ESA, contrary to Rule 2-032(4) of the Ontario Electrical Safety Code.



Administrative Action Summary

	Campoli Electric Ltd., was ordered to pay an administrative penalty of \$1,000.
Description of Contravention	Campoli Electric Ltd., ("Campoli") is a Licensed Electrical Contractor.
	Between April 11, 2024, and December 17, 2024, Campoli connected or reconnected an installation or part thereof at two (2) multi-residential properties in Mississauga, Ontario, to a service or other source of supply without a connection authorization issued by the ESA.
	Between April 11, 2024, and December 17, 2024, Campoli removed tags, seals or warnings applied to an electrical installation or applied to electrical equipment at two (2) multi-residential properties in Mississauga, Ontario, by the ESA without permission from the ESA.
Additional Information	