

Administrative Action Summary

Date	March 14, 2025
Name	1084999 Ontario Inc. o/a Total Fire Protection
Licensure Status at Time of Incident	Unlicensed
Administrative Action	Administrative Penalty
Location	Ottawa, Ontario
Regulation Description	<p>1. Operated an electrical contracting business, 1084999 Ontario Inc., o/a Total Fire Protection, without being the holder of an electrical contractor license, contrary to s. 3 of Ontario Regulation 570/05: Licensing of Electrical Contractors and Master Electricians.</p> <p>1084999 Ontario Inc., o/a Total Fire Protection, was ordered to pay an administrative penalty of \$3,000.</p> <p>2. Carried out an activity referred to in the regulations under the Act as requiring an authorization, by carrying out electrical work at a residential property in Ottawa, contrary to ss.113.2(1) of the <i>Electricity Act, 1998</i>.</p> <p>1084999 Ontario Inc., o/a Total Fire Protection, was ordered to pay an administrative penalty of \$4,000.</p> <p>3. Prior to the commencement of work to be done on an electrical installation at a residential property in Ottawa, failed to file with the Electrical Safety Authority, a Notification of Work, contrary to Rule 2-004(1)(a) of the Ontario Electrical Safety Code.</p> <p>1084999 Ontario Inc., o/a Total Fire Protection, was ordered to pay an administrative penalty of \$1,000.</p>

Administrative Action Summary

Description of Contravention	<p>1084999 Ontario Inc., o/a Total Fire Protection, (“TFP”), was not authorized (licensed) to operate an electrical contracting business.</p> <p>Between October 23, 2023 and October 25, 2023, TFP operated an electrical contracting business, 1084999 Ontario Inc., o/a Total Fire Protection, at a commercial property while not the holder of an electrical contractor license.</p> <p>TFP was not authorized to carry out electrical work.</p> <p>Between October 23, 2023 and October 25, 2023, TFP carried out electrical work at a commercial property in Ottawa.</p> <p>Between October 23, 2023 and October 25, 2023, and prior to the commencement of work to be done on an electrical installation at a commercial property in Ottawa, TFP failed to file a Notification of Work, colloquially known as a ‘permit’.</p>
Additional Information	