

Date	March 28, 2024
Name	Sukhman Singh Khangura
Licensure Status at Time of Incident	Unlicensed
Administrative Action	Administrative Penalty Order
Location	Toronto
Regulation Description	<p>Khangura operated an electrical contracting business, 5037394 Ontario Inc., which operated as TDOT Electric and Construction, when Khangura was not the holder of an electrical contractor license, contrary to s.3 of O. Reg. 570/05: Licensing of Electrical Contractors and Master Electricians.</p> <p>Khangura was ordered to pay an administrative penalty of \$3,000.</p> <p>Prior to the commencement of work done on an electrical installation at a residential property located in Clarington, Ontario, Khangura failed to file with Electrical Safety Authority a notification of the work, contrary to rule 2-004(1)(a) of the Ontario Electrical Safety Code.</p> <p>Khangura was ordered to pay an administrative penalty of \$3,000.</p>
Description of Contravention	<p>Between September 1, 2022, and September 12, 2023, Khangura operated an electrical contracting business, 5037394 Ontario Inc., which operated as TDOT Electric and Construction, when Khangura was not the holder of an electrical contractor license. Khangura then commenced work on an electrical installation at a residential property located in Clarington, Ontario. Prior to commencing electrical work, Khangura failed to</p>



Administrative Action Summary

	file a notification of work (a.k.a. a permit) with the Electrical Safety Authority.
Additional Information (if necessary)	